CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM					Pageof
Sewershed: Dundalk		Consultant: RJN Group, Inc.		oup, Inc.	Date: YYYYMMDD ての名 」!! 」でし
Test to be performed: Smoke Dye _✓		Dry	Ground Conditi Damp		Supervisor initials:
Manhole ID: S67kA02 MH		Test ID:	D1047-	• •	Notifications - made daily: <u>&lt;</u> (Residents, Fire, 311)
Field Sketch: Show names, building add					Ibag or isolation device location, street ers.
St St	-> O- S67KA07	<del></del>	K Aoi Oxid	567K-006	Dipressed Grass Area  25 min- SD gallows  Dy 2 Test positive  Dy 1 testing Joints  WH WAILS leaking Joints  Leaking frame adjustment  leaking frame frame aljustment  leaking of frame  Hudson St
					<b>rjn</b> group

CITY OF BALTIMORE WET WEATH DYED WATER	Pageof	
Sewershed: Dundalk	Consultant: RJN Group, Inc.	Date: YYYYMMDD 2008   IL   2 (
Test to be performed: Smoke Dye	Ground Condition: Dry Damp <u>✓</u> Wet	Supervisor initials:
Manhole ID: S67kA02 MH	Test ID: D1047-296	Notifications - made daily: <u>···</u> (Residents, Fire, 311)

**Field Sketch:** Show all manholes with numbers, blower placement location, sandbag or isolation device location, street names, building addresses and locations, defect locations and photograph numbers.






D1047-296-OB01-P01

D1047-296-OB01-P02







D1047-296-OB01-P04

**rjn**group